

**From:** [Moore, Gary](#)  
**To:** [Cassidey, LeRoy](#)  
**Cc:** [Crawford, Beth](#)  
**Subject:** CES: Incineration at Clean Harbors  
**Date:** Thursday, September 04, 2014 10:12:39 PM

---

**Leroy:**

**I had a conversation with IKON Environmental and they just got rid of some materials at Clean Harbors incinerator that were similar in nature to VB25141, VB2567, and VB640. They indicated that Clean Harbors will not enter the boxes to remove the heel so when it went to the cleaning facility, they had to have the cleaning facility drum the remaining material and then profile the drum back into Clean Harbors for disposal. I am not sure there is anything we can do to make sure that we do not run into this issue but its something we need to think about.**

**Thanks**

**Gary Moore**

**Federal On-Scene Coordinator**

**U.S. EPA Region 6**

**214-789-1627 cell**

**214-665-6609 office**

**[moore.gary@epa.gov](mailto:moore.gary@epa.gov)**